



## Sulfamic Acid

<b>Formula</b>	<b>NH<sub>2</sub>SO<sub>3</sub>H</b>
Description	Non-hygroscopic, odorless, colorless crystals
Melting point	205°C with decomposition
Solubility	Moderately soluble in water, slightly soluble in ethanol, methanol and acetone, insoluble in diethyl ether
Appearance	White crystalline solid
Purity	99.8% min.
Insoluble matter	0.01% max.
Ash	0.01% max.
Sulfate	0.05% max.
Iron	0.0005% max.
Lead	0.0001% max.
Heavy metals	0.0001% max.
Moisture	0.1% max.
Chlorine	0.001% max.
Bulk density	1.0 – 1.3